

Case Study on quality control tools for Bearing industries

Shraddha Arya¹, Manish Bhargava², MP Singh³

(Research Scholar, Department of Mechanical Engineering, Jagannath University, Rajasthan, India.)¹

(Principal, Maharishi Arvind Institute of Engineering and Technology, Rajasthan, India.)²

(Professor, Department of Mechanical Engineering, JECRC University, Rajasthan, India.)³

Abstract: -

In this paper a review of systematic use of 7 QC tools for improving the quality of deep groove ball bearing is presented. QC tools are the means for Collecting data, analyzing data, identifying root causes and measuring the results. Quality Control tools are related to numerical data processing techniques. All of these tools together can deliver prodigious process chasing and analysis that can be very helpful for quality developments. These tools make quality improvements easier to see, implement and track, using 7 QC in mini tab, graphs can be easily calculated with dimension.

Keywords: Deep groove ball bearing, Mini-Tab, optimal result, Quality Control.

1.1 INTRODUCTION: -

The 7 QC Tools are simple statistical tools used for problem solving in different sectors. These tools were initially developed in Japan by Deming and Juran. In terms of importance, these are the most useful. Kaoru Ishikawa has specified that these 7 tools can be used to solve 95 percent of all problems. These tools have been the base of Japan's astonishing industrial renaissance.

In today's era more than a hundred different tools are available to solve problems for giving accurate results and saving time. Tools are generally a means of achieving change and in this paper we will focus on the most fundamental quality tools which are commonly used in many software's called the seven basic quality control tools 7 QC Tools: -Cause and Effect Diagram, Graphs / Flowcharts, Pareto analysis, Check sheets, Control charts, Scatter diagram, Histogram.

These tools are used to find out root causes and eradicates then, thus the manufacturing process can be enhanced. The procedures of defects on manufacture line are examined through direct remark on the production line and statistical tools.

1.2 METHODOLOGY AND APPLICATION OF 7QC TOOLS: -

These simple but effective "tools of improvement" are widely used as "graphical problem-solving methods" and as general management tools in every process between design and delivery. The challenge for the manufacturing and production industry is for: "Everyone to understand and use the improvements tools in their work". Some of the the seven tools can be used in process identification and/or process analysis.

1.2.1 CAUSE AND EFFECT DIAGRAM

It shows the relationship between a problem and its possible causes.

A systematic arrangement of all possible causes which give rise to the effect are made. The causes are first divided into major sources (4Ms) i.e., MAN, MACHINE, METHOD & MATERIAL. Then each source is divided into sub-sources and so on. It helps to find out the root cause of the problem.





Fig. Cause and Effect Diagram

1.2.2 Flow Chart / Graphs


Flow Chart: A Tool that graphically represents the steps of a process. Different icons/symbols to indicate the different types of actions in the process.

(a) Bar Graph




(b) Pie Chart: A graph for the proportion of the different classifications

1.2.2 **Line graph:** A graph to see the changes in condition of any numeric changes



1.2.3 PARETO DIAGRAM –



1.2.4 CHECK SHEET :

A check sheet is a paper form on which items to be checked have been printed so that data can be collected easily and concisely. Its main purpose is twofold.

- To make data gathering easy
- To arrange data automatically so that they can be used easily later on.

It is necessary to decide clearly how to record the defects. When these are found in a product. We should give proper instructions to the staff regarding the format in which the defects are to be gathered. In this case, 42 out of 1525 components were found defective. However, the total nos of defects was 62 because two or more defects were found on the same piece.

1.2.5 CONTROL CHARTS:

Control charts serve to detect abnormal trends with the help of line graphs. It differs from standard line graphs as they have control limit lines at the center, top and bottom levels.

CONTROL CHARTS FOR VARIABLES

- **The variable control charts that are most commonly used are average or X-bar-charts, range or R-chart and sigma-standard deviation charts.**

1.5.1 X CHART

X chart shows the centering of the process, i.e. it shows the variation in the average of samples. It is the most commonly used variable chart.



1.2.6 HISTOGRAM :


A diagram that graphically depicts the variability in a population. The frequency data obtained from measurements display a peak around a certain value. The variation of quality characteristics is called distribution. The figure that illustrates frequency in the form a pole is referred to as a Histogram.

POPULATION AND SAMPLE

The entire set of items is called the Population. The small number of items taken from the population to make a judgment of the population is called a Sample. The numbers of samples taken to make this judgment is called Sample size.

1.2.7 Scatter Diagram





1.2.7 SCATTER DIAGRAM

Two variables :

- a) Speed of the car in kms / Hr.
- b) Petrol consumption in kms / Lt.

Speed of the car in kms / Hr.	Petrol consumption in kms / Lt.
30	15, 15.5
35	16, 16.5
40	17, 17.5
45	18, 18.5
50	19, 19.5
55	20, 20.5
60	22, 22.5
65	21, 21.5
70	20, 20.4
75	19, 19.6
80	18, 18.6
85	18, 18.5
90	17, 17.4
95	16, 16.2


100	16, 16.1
-----	----------

Here:-

Cause : Speed of the car in kms / Hr.

Effect : Petrol consumption in kms / Lt

Positive and negative co-relation



1.3.1 X CHART -

X chart shows the centering of the process, i.e. it shows the variation in the average of samples. It is the most commonly used variable chart.

1.3.2 R CHART -

R chart shows the uniformity or consistency of the process i.e. it shows the variation in the range of samples.

Diameter of Shaft: $23.75 + 0.1$ mm

No. of samples per day : 6

The diameter of shafts are as given below :

1 st day	2 nd day	3 rd day	4 th day	5 th day	6 th day	7 th day	8 th day
23.77	23.80	23.77	23.79	23.75	23.78	23.76	23.76
23.80	23.78	23.78	23.76	23.78	23.76	23.78	23.79
23.78	23.76	23.77	23.79	23.78	23.73	23.75	23.77
23.73	23.70	23.77	23.74	23.77	23.76	23.76	23.72
23.76	23.81	23.80	23.82	23.76	23.74	23.81	23.78
23.75	23.77	23.74	23.76	23.79	23.78	23.80	23.78

Construct the X and R chart:

Average diameter for the first day

$$X1 = X1+X2+X3+X4+X5+X6$$

$$= \frac{23.77+23.80+23.78+23.73+23.76+23.75}{6}$$

$$= 23.765$$

Similarly, the averages for each day are calculated:

X1	X2	X3	X4	X5	X6	X7	X8
23.765	23.77	23.7716	23.7767	23.7717	23.7583	23.7767	23.7667

$$\text{Now } \bar{X} = \frac{X = 190.1567}{N = 8} = 23.7696$$

Ranges :

R1	R2	R3	R4	R5	R6	R7	R8
.07	.11	.06	.08	.04	.05	.06	.07

$$R = \frac{R = 0.0675}{N}$$

For X chart:

$$\begin{aligned}UCLX &= \bar{X} + A_2R \\ &= 23.7696 + 0.48 \times 0.0675 \\ &\text{(A}_2= 0.48 \text{ for subgroup of from table)} \\ &= 23.7696 + 0.0324 = 23.802 \\ LCLX &= \bar{X} - A_2R\end{aligned}$$

$$= 23.7696 - 0.0324 = 23.7322$$

For R chart :

$$\begin{aligned}UCLR &= D_4R \\ &= 2 \times 0.0675 = 0.1350 \\ LCRR &= D_3R \\ &= 0 \text{ (D}_3 = 0 \text{ for subgroup of 6 or less)}\end{aligned}$$

Process capability: $\sigma = R / d_2 = 0.0675 / 2.534 = 0.0266$
(for subgroup of 6, $d_2 = 2.534$)

X max = (USL) upper specification limit, X min. = (LSL) lower specification limit

1.4 Types of Variation in 7 Quality Tools

- 1) Variation due to chance causes
- 2) Variation due to assignable causes.

1) Variation due to chance causes:

Variations due to chance causes are inevitable in any process or product. They are difficult to trace and difficult to control even under best conditions of production. Since these variations may be due to some inherent characteristic of the process or machine which functions at random. For example, a little play between nut and screw at random may lead to back-lash error and may cause a change in dimension of a machined part.

2) Variation due to assignable causes:

These variations possess greater magnitude as compared to those due to chance causes and can be easily traced or detected. The variations due to assignable causes may be because of the following factors:

- a) Differences among machines.
- b) Differences among workers
- c) Differences among materials
- d) Change in working conditions

$$X_{\max} - X_{\min} = 0.2 \text{ mm from data}$$

Process capability $C_p = (USL - LSL) / 6 \text{ sigma}$

$$C_p = 0.2 / 6 * 0.0266 = 0.2 / 0.15982 = 1.25$$

$C_{pk} = (USL - \bar{X}) / 3 \text{ sigma}$ or $(\bar{X} - LSL) / 3 \text{ sigma}$

$$C_{pk} = (23.85 - 23.7696) / 3 * 0.0266 = 1.0$$

$$C_{pk} = (23.7696 - 23.65) / 3 * 0.0266 = 1.49$$

$C_{pk} = 1.0$ or 1.49 (1.0 is minimum)

1.5 Conclusion: -

Tools are simple, very powerful and help to identify the causes for work related problems and to find solutions for the same in a systematic manner. Quality Control tools are basically concerned in making sure that numerous procedures and occupied arrangements are in place to provide for effective and efficient statistical processes, to minimize the risk of errors or weaknesses in procedures or systems or in source material.

Seven QC tools are most helpful in troubleshooting issues related to quality, all processes are affected by multiple factors and therefore numerical QC tools can be practical for any procedure.

IJSER

References :-

1. Application of 7 Quality Control (7 QC) Tools for Continuous Improvement of Manufacturing Processes Varsha M. Magar¹, Dr. Vilas B. Shinde², International Journal of Engineering Research and General Science Volume 2, Issue 4, June-July, 2014 ISSN 2091-2730.
2. Basic Quality Tools in Continuous Improvement Process Mirko Soković^{1,*} - Jelena Jovanović² - Zdravko Krivokapić² - Aleksandar Vujović², Strojniški vestnik - Journal of Mechanical Engineering 55(2009)5, UDC 658.5
3. Application of quality control tools in a bicycle industry: a case study, Deepak¹, Dheeraj Dhingra², IJRET: International Journal of Research in Engineering and Technology eISSN: 2319-1163 | pISSN: 2321-7308.
4. Basic Quality Tools in Continuous Improvement Process, Mirko Soković^{1,*} - Jelena Jovanović² - Zdravko Krivokapić² - Aleksandar Vujović², Strojniški vestnik - Journal of Mechanical Engineering 55(2009)5, StartPage-EndPage UDC 658.5.
5. Improve the Quality of Tablets by Statistical Tools Syed Ebad Ali¹, Abdullah Jabber², Adnan Zahid³, Irfan Amin⁴, Akhter Yaseen⁵, IOSR Journal Of Humanities And Social Science (IOSR-JHSS), Volume 20, Issue 4, Ver. II (Apr. 2015), PP 64-69 e-ISSN: 2279-0837, p-ISSN: 2279-0845.
6. Improvement of Productivity by application of Basic seven Quality control Tools in manufacturing industry Chiragkumar S. Chauhan¹, Sanjay C. Shah², Shrikant P. Bhatgalikar³, International Journal of Advance Research in Engineering, Science & Technology ISSN No:Applied.
7. Seven Basic Tools of Quality Control: An Appropriate Tools for Solving Quality Problems in the Organizations, Behnam Neyestani, MPRA Paper No. 77681, posted 20 March 2017 16:23 UTC.
8. Seven Basic Tools of Quality Control: The Appropriate Techniques for Solving Quality Problems in the Organizations, Behnam Neyestani, De La Salle University, Civil Engineering 2017.
9. UTILIZATION OF QUALITY TOOLS: DOES SECTOR AND SIZE MATTER?, Luis Fonseca 1 Vanda Lima Manuela Silva, International Journal for Quality Research 9(4) 605–620 ISSN 1800-6450.
10. Similarities and differences between TQM, six sigma and lean Roy Andersson, Henrik Eriksson and Ha°kan Torstensson, The TQM Magazine Vol. 18 No. 3, 2006, pp. 282-296.
173. Acoustic emission analysis of deep groove polyacetal (pom) ball bearing attel manjunath*¹ & dr. D.v. girish², international journal of engineering sciences &management, issn 2277 – 5528, impact factor-4.015, march 2017.